

Manhattan

Manhattan SX v1.03 Release Notes (22/11/18)

Issues Fixed

- Deleted channels were being added back again after the SX performed the Automatic Service Update during standby.
- SCR could sometimes be active during Install even though the user had not selected it. This would cause the installation to fail in a non-SCR environment.
- No Audio/Video could be displayed when exiting a Freesat Retune during signal lock.