

# Manhattan

## Manhattan T3•R v2.05 Release Notes (23/05/23)

### New

- ITVX is supported and will be accessible from the Home Screen from Thursday 25th May 2023.

### Improved

- Lip-sync can now be adjusted in 10ms increments (previously 20ms).

### Resolved

- When browsing backwards in the TV Guide for catch-up content, the T3-R could reboot when using the P-UP/P-DOWN buttons or entering channel numbers with the number buttons.
- When playing an ongoing recording immediately after using an interactive service like Channelbox (channel 271), if you fast forwarded to the live point and then tried to pause or rewind live TV, the error message 'This function is unavailable with interactive services' would be shown incorrectly.
- When playing an ongoing recording and fast forwarding to the live point, the playback position was not saved.
- When a recording was stopped, deleted and then started again, the new recording would show in the Trash.
- When playing an ongoing recording immediately after viewing a channel from a different multiplex, fast forwarding to live, rewinding, and then fast forwarding back to live would result in the loss of audio/video.
- When a series episode was broadcast simultaneously on two or more channels, it could be recorded on a different channel than the one originally scheduled for the recording.
- When a recording was scheduled on a channel but an alternative broadcast was recorded on a different channel, a second entry stating the recording had failed could be found in the Recordings menu
- When rewinding recorded radio programmes, playback would jump back to the point before you started rewinding.

- When Auto Standby was disabled and the T3-R was left on overnight on a channel with broadcasting breaks like Blaze (channel 64), recordings on that channel could fail.
- When playing back a recording and fast forwarding or rewinding, the audio/video could freeze.
- When recording continuously for 2 or more days, repeated programmes could be recorded again.
- When recording continuously for 2 or more days, the T3-R could become unresponsive while audio/video continued.
- When creating a child profile in BBC iPlayer, the T3-R would reboot when entering the month in their date of birth.
- When resuming HDR content in iPlayer, the TV could fail to switch to HDR.
- When HDMI-CEC was enabled, some TVs could wake up unexpectedly.